

Warranty Vehicle Inquiry

Mon Sep 25, 2017 10:34:54 EDT

VIN(Last Seven) : DT83081 CONFIDENTIAL

THIS DOCUMENT IS NOT TO BE USED OR RELIED UPON FOR IMPORT OR EXPORT PURPOSES AND IS NOT TO BE DISTRIBUTED OR SHARED WITH THIRD PARTIES*

*EXCEPT FOR SPECIFIC INFORMATION THAT MAY BE REQUIRED BY LAW

DO NOT USE DAVIS AS THE SOLE INDICATOR FOR CALCULATING VEHICLES' DAYS OUT OF SERVICE. DAVIS IS A GUIDE ONLY AND DOES NOT INCLUDE EXACT NUMBERS AS CONFLICTS IN DAYS TO CLOSE A REPAIR ORDER MAY EXIST.

© 2017 BMW of North America, LLC

WFO@ValeriusSport.com

Vehicle Data

| | |
|---|--|
| VIN: WBAHN83548DT83081 | Davis #: 16 |
| Chassis Number: DT83081 | Assist Safety Plan Expires: 03/31/2015 |
| Line Make: 01 - BMW Car | Assist Conv. Plan Expires: 00/00/0000 |
| Model Year: 2008 | TCU ESN / TCU IMEI: 10215508823 INACTIVE |
| AG Model Code/Desc: HN83 - 750LI SEDAN | TCU MIN: XXX-XXX-XXXX |
| NA Model Code/Desc: 0879 - 750Li Sedan | MDN / MSISDN: XXX-XXX-XXXX |
| Motor Type: N62T | Vehicle Production Date: 2008/01 |
| Exterior Trim Code: 475 - Black Sapphire Metallic | Series: E66 |
| Interior Color Code: U6SW - Black Nasca Leather | Wholesale Center ID/Loc: 75784-01 |
| MSRP: \$91,470.00 | Wholesale Date: 03/10/2008 |
| | Retail Center ID/Loc: 75784-01 |
| | Retail Date: 03/31/2008 |
| | In-Service Date: 03/31/2008 |

Open Campaign Information

| Stop Sale | Stop Code | Defect Code | Defect Description | Bulletin Number | Recall Number | Campaign Status | Reserved By, Reserved Date |
|-----------|-----------|-------------|--|-----------------|---------------|-----------------|----------------------------|
| STOP | | 00511770400 | B512417 Recall - Door Latch - Do not retail or deliver | B51 24 17 | 17V-328 | 00-Open | |

Option Information

| Code | Description | Code | Description |
|------|-----------------------|------|------------------------------|
| 0ZCV | Convenience Package | 0ZLS | Luxury Seating Package |
| 0ZPS | Premium Sound Package | 0ZRP | Rear Entertainment Package |
| 0ZSP | Sport Package | 0330 | Sport Pkg w/Sport Suspension |

| | | | |
|------|------------------------------|------|--------------------------------|
| 01CA | CO2 relevant vehicles | 02VB | Tire pressure monitor |
| 0322 | Comfort Access keyless entry | 0358 | Infrared windshield |
| 0423 | Floor mats | 0430 | Auto-dimming mirrors |
| 0441 | Smoker's package | 0456 | Multi-contour seats |
| 0494 | Heated front seats | 0508 | Park Distance Control |
| 0524 | Adaptive light control | 0609 | Navigation system |
| 0620 | Voice command | 0655 | SiriusXM Radio w/ 1 year sub. |
| 0691 | CD holder | 0697 | DVD Area coding, North America |
| 08SP | CO2 control | 0925 | Shipping package |
| 0ZFA | First aid kit | | |

Customer Information

Name (First/Last):
Address:

| Warranty/Maintenance Programs/Contract Services/Administered by BMW NA | | | | | | | | | | | | |
|--|---|--|------------|-------------|-------------------|---------------|----------------------|-------------------|---------------|-----------------------------------|------------------|------------------------------|
| Type | Warr/Program Codes/Desc | Contract Number/Status | Eff Date | Enroll Date | No Coverage As Of | Exp Age (Mth) | Exp Odometer (Miles) | Current Age (Mth) | Retail Center | Center Name | Vendor Code Used | Contract Holder (First/Last) |
| MP | New Vehicle Limited Warranty | 0000000 EXPIRED | 03/31/2008 | | 03/31/2012 | 48 | 50,000 | 114 | | | | |
| MP | 000000168 - MP 48 MO/050K MLS | 0000000 EXPIRED | 03/31/2008 | 03/31/2008 | 03/31/2012 | 48 | 50,000 | 114 | 75784 | Lauderdale BMW of Fort Lauderdale | MP | |
| ESC | 0000000039 - ESC PL 84M/70K MIs | 0044612 EXPIRED | 03/31/2008 | 02/28/2012 | 03/31/2015 | 84 | 70,000 | 114 | 46697 | Vista BMW | PL | THOMAS CLARK |
| FE | Federal Emissions 8/80 FE 96 MO/80K MLS | 0000000 EXPIRED | 03/31/2008 | 03/31/2008 | 03/31/2016 | 96 | 80000 | 114 | 75784 | Lauderdale BMW of Fort Lauderdale | 00 | |
| CA | California Emissions | Vehicle may qualify for California Emissions Coverage. Please verify if the vehicle was sold or is registered in a California Emissions Covered State (AZ,CA,CT,DE,MA,MD,ME,NJ,NM,NY,OR,PA,RI,VT,WA). Please confirm model year, selling state and current registration of the vehicle and click here to determine coverage. | | | | | | | | | | |

Attention: Please verify customer information against contract holder before submitting any ESC claims

THIS DOCUMENT IS NOT TO BE USED OR RELIED UPON FOR IMPORT OR EXPORT PURPOSES AND IS NOT TO BE DISTRIBUTED OR SHARED WITH THIRD PARTIES.
EXCEPT FOR SPECIFIC INFORMATION THAT MAY BE REQUIRED BY LAW
DO NOT USE DAVIS AS THE SOLE INDICATOR FOR CALCULATING VEHICLES' DAYS OUT OF SERVICE. DAVIS IS A GUIDE ONLY AND DOES NOT INCLUDE EXACT NUMBERS AS CONFLICTS IN DAYS TO CLOSE A REPAIR ORDER MAY EXIST.
© 2017 BMW of North America, LLC

| Repair History (Claims) | | | | | | | | | | |
|-------------------------|-------------|--------------|------------|----------------|-------------------|-------------------|---------|---------|-------------|---|
| Center ID | Location ID | Claim Number | Claim Date | Repair Order # | Repair Order Date | Repair Entry Date | Davis # | Mileage | Defect Code | Description |
| 46697 | 03 | 2959 | 02/25/2015 | 115447 | 02/21/2015 | 02/25/2015 | 0 | 60,318 | 9999977PL | DEDUCTIBLE |
| 46697 | 03 | 2950 | 02/25/2015 | 115447 | 02/21/2015 | 02/25/2015 | 0 | 60,318 | 12310048PL | ALTERNATOR LEAKING |
| | | | | | | | | | 61125579PL | COIL SPRING CASSETTE INCORRECT CONNECTION /CONTACT |
| | | | | | | | | | 9999977PL | DEDUCTIBLE |
| 75784 | 01 | 714139 | 11/13/2014 | 399208 | 11/12/2014 | 11/13/2014 | 0 | 57,696 | 51231066PL | ENGINE HOOD GAS SPRING NO EFFECT |
| 75784 | 01 | 714130 | 11/13/2014 | 399208 | 11/12/2014 | 11/13/2014 | 0 | 57,696 | 9999977PL | DEDUCTIBLE |
| 75784 | 01 | 484919 | 05/15/2014 | 385475 | 05/14/2014 | 05/15/2014 | 0 | 51,253 | 9999977PL | DEDUCTIBLE |
| 75784 | 01 | 484910 | 05/15/2014 | 385475 | 05/14/2014 | 05/15/2014 | 0 | 51,253 | 11140048PL | TIMING CASE COVER, TOP LEAKING |
| | | | | | | | | | 64520014PL | AIR CONDITIONING COMPRESSOR OCCASIONAL MALFUNCTION |
| 75784 | 01 | 415369 | 03/20/2014 | 381308 | 03/19/2014 | 03/20/2014 | 0 | 49,651 | 9999977PL | DEDUCTIBLE |
| 75784 | 01 | 415360 | 03/20/2014 | 381308 | 03/19/2014 | 03/20/2014 | 0 | 49,651 | 11130248PL | OIL SUMP GASKET(BOTTOM)-LEAKING |
| | | | | | | | | | 51331229PL | WINDOW REGULATOR, FRONT STICKING/JAMMED |
| | | | | | | | | | 64530948PL | Pressure switch/pressure sensor Leaking |
| | | | | | | | | | 67310312PL | ACTUATOR DRIVE, THIGH SUPPORT FAILED |
| 75784 | 01 | 301341 | 01/10/2014 | 374235 | 12/05/2013 | 01/10/2014 | 0 | 47,014 | 24003561PL | SHIFT QUALITY M/S GATE, UPSHIFT, AUTOMATIC TRANSMISSION TOO ROUGH |
| 75784 | 01 | 301349 | 12/10/2013 | 374235 | 12/05/2013 | 12/10/2013 | 0 | 47,014 | 9999977PL | DEDUCTIBLE |
| 75784 | 01 | 301348 | 12/10/2013 | 374235 | 12/05/2013 | 12/10/2013 | 0 | 47,014 | 9999977CF | CORE CREDITS - AUTOMATIC VIA IWS - JACKSONVILLE PDC |
| 75784 | 01 | 301340 | 12/10/2013 | 374235 | 12/05/2013 | 12/10/2013 | 0 | 47,014 | 12310048PL | ALTERNATOR LEAKING |
| | | | | | | | | | 24003561PL | SHIFT QUALITY M/S GATE, UPSHIFT, AUTOMATIC TRANSMISSION TOO ROUGH |
| 75784 | 01 | 213859 | 09/12/2013 | 368430 | 09/10/2013 | 09/12/2013 | 0 | 45,107 | 9999977PL | DEDUCTIBLE |
| 75784 | 01 | 213850 | 09/12/2013 | 368430 | 09/10/2013 | 09/12/2013 | 0 | 45,107 | 11140048PL | TIMING CASE COVER, TOP LEAKING |
| | | | | | | | | | 24004948PL | Leak at gearbox output (output end), automatic transmission leaking |
| | | | | | | | | | 64510048PL | Air conditioning evaporator, front Leaking |
| 75784 | 01 | 90850 | 05/22/2013 | 360675 | 05/21/2013 | 05/22/2013 | 7 | 41,863 | 0065600200 | B651213 Recall Program Control Units (Central Gateway Module) |

THIS DOCUMENT IS NOT TO BE USED OR RELIED UPON FOR IMPORT OR EXPORT PURPOSES
AND IS NOT TO BE DISTRIBUTED OR SHARED WITH THIRD PARTIES.

*EXCEPT FOR SPECIFIC INFORMATION THAT MAY BE REQUIRED BY LAW

DO NOT USE DAVIS AS THE SOLE INDICATOR FOR CALCULATING VEHICLES' DAVIS OUT OF SERVICE.
DAVIS IS A GUIDE ONLY AND DOES NOT INCLUDE EXACT NUMBERS AS CONFLICTS IN DAVIS TO CLOSE A REPAIR ORDER MAY EXIST.
© 2017 BMW of North America, LLC

| Center ID | Location ID | Claim Number | Claim Date | Repair Order # | Repair Order Date | Repair Entry Date | Davis # | Mileage | Defect Code | Description |
|-----------|-------------|--------------|------------|----------------|-------------------|-------------------|---------|---------|-------------|--|
| 46697 | 01 | 886400 | 02/29/2012 | 465593 | 02/28/2012 | 02/29/2012 | 0 | 30,128 | 85990101MP | VEHICLE CHECK |
| | | | | | | | | | 85990501MP | STANDARD OPERATION MP |
| 75784 | 03 | 532230 | 11/17/2011 | 201444 | 11/15/2011 | 11/17/2011 | 0 | 27,034 | 34000077MP | BRAKE FLUID CHANGE- FULL MAINTENANCE PROGRAM |
| | | | | | | | | | 61610077MP | FT WIPER RUBBER INSERT-MP |
| | | | | | | | | | 64310237MP | MICROFILTER REPLACEMENT |
| | | | | | | | | | 85990501MP | STANDARD OPERATION MP |
| 75784 | 03 | 432120 | 07/28/2011 | 193593 | 07/26/2011 | 07/28/2011 | 0 | 23,857 | 85990091MP | OIL SERVICE(MP)AFTER THE 1ST |
| | | | | | | | | | 85990501MP | STANDARD OPERATION MP |
| 75784 | 03 | 318820 | 04/06/2011 | 185844 | 03/31/2011 | 04/06/2011 | 3 | 21,249 | 5133121300 | Power window, front broken |
| | | | | | | | | | 85990087MP | MP-LOW MILEAGE ANNUAL OIL SERVICE |
| 75784 | 03 | 203290 | 12/20/2010 | 178672 | 12/16/2010 | 12/20/2010 | 2 | 19,189 | 0034910100 | Recall Inspect Brake Booster Vacuum Supply Line |
| 75784 | 03 | 117270 | 09/27/2010 | 172483 | 09/24/2010 | 09/27/2010 | 0 | 16,252 | 61610077MP | FT WIPER RUBBER INSERT-MP |
| 75784 | 01 | 799700 | 11/18/2009 | 271624 | 11/13/2009 | 11/18/2009 | 4 | 10,269 | 0012610200 | E65, E66 US MY 2008 - N62TU, N73 Program control units (freeze frame) B12-17 |
| 75784 | 01 | 799690 | 11/18/2009 | 271624 | 11/13/2009 | 11/18/2009 | 0 | 10,269 | 34000077MP | BRAKE FLUID CHANGE- FULL MAINTENANCE PROGRAM |
| | | | | | | | | | 61610077MP | FT WIPER RUBBER INSERT-MP |
| | | | | | | | | | 64310237MP | MICROFILTER REPLACEMENT |
| | | | | | | | | | 85990089MP | 1ST ENG OIL SERVICE-FULL MAINTENANCE |
| | | | | | | | | | 85990501MP | STANDARD OPERATION MP |
| 75784 | 03 | 116160 | 03/11/2008 | 102208 | 03/10/2008 | 03/11/2008 | 0 | 2 | 11999977BV | QC1 SPOT DELIVERY |

End of Print

THIS DOCUMENT IS NOT TO BE USED OR RELIED UPON FOR IMPORT OR EXPORT PURPOSES AND IS NOT TO BE DISTRIBUTED OR SHARED WITH THIRD PARTIES.

EXCEPT FOR SPECIFIC INFORMATION THAT MAY BE REQUIRED BY LAW

DO NOT USE DAVIS AS THE SOLE INDICATOR FOR CALCULATING VEHICLES' DAVIS OUT OF SERVICE. DAVIS IS A GUIDE ONLY AND DOES NOT INCLUDE EXACT NUMBERS AS CONFLICTS IN DAVIS TO CLOSE A REPAIR ORDER MAY EXIST.

© 2017 BMW of North America, LLC